

SALVAGE TENDER

1947 Cessna 140, N2933N, S/N: 12753

TENDER CONDITIONS

The salvage of the above aircraft is offered in a damaged condition for public tender, on an "as- is, where-is" with all faults basis subject to these Terms and Conditions and Salvage Tender Agreement. In particular, please read the section "Important Terms and Conditions" at the back of the Agreement.

Date of Loss: 11/30/2024

Loss Location: Pearland, TX

Occurrence: Aircraft nosed over after 3 point landing

Bids shall be submitted no later than close of business on <u>06/12/2025</u> 12:00PM PST/3:00PM EST/2:00PM CST

- 1. Bids are to be in United States Dollars.
- 2. The highest bid or tender will not necessarily be accepted.
- 3. Once the successful Tenderer is notified that their bid has been accepted, the full purchase price must be deposited into a nominated account within **fifteen (15) days** of that notification, at which point risk of all loss in the salvage shall pass to the Tenderer.
- 4. The completion of the sale of the salvage and the transfer of title to the successful Tenderer will be subject to the execution of the form of FAA Bill of Sale by the Owner(s).
- 5. Aircraft storage costs will be for the Tenderer's account accruing from **thirty (30) days** after the salvage award date.
- 6. McLarens Aviation, the Owner and/or Insurers make no representation whatsoever concerning the accuracy of information supplied, and the Tenderer acknowledges that regardless of whether they have inspected the salvage they are bidding on their own judgment of the condition of the salvage and records.



AIRCRAFT SALVAGE DATA

Year: <u>1947</u> Make: <u>Cessna</u> Model: <u>140</u> N#: <u>2933N</u> S/N: <u>12753</u>

Airframe Total Time: 2392.3

Engine(s):

#1 Make Continental Model C-85-12 S/N 26789-6-12 TT 2392.3 SMOH 215.8

#2 Make ---- Model ---- S/N ---- TT ---- SMOH ----

Propeller(s):

#1 Make McCauley Model 1A9A/CF1748 S/N 9136 TT 2392.3 SMOH 329.24

#2 Make ---- S/N ----- TT ----- SMOH -----

Avionics Equipment:

QTY **MAKE MODEL** KT76A 1 King <u>1</u> Uavionix **Tailbeacon** Garmin **GNC 300XL** 1

Additional Equipment (Mods/Alterations): Enigne Modified by STC SE00979AT (O200 Crankshaft), Airwolf Remote Oil Filter, EAA Auto Fuel STC, Aero fabricator shoulder harness

AIRCRAFT DAMAGE DETAILS

General Description of Damage: From NTSB report: upper portion of vertical stabilizer and rudder substantially damaged. Prop Overhaul and engine teardown required due to prop strike. Wrinkled skins aft of firewall right side, left side fuselage wrinkled aft of cabin

Additional Notes Regarding Logs, Items Missing, Etc.: The logs engine and airframe appear to go from new(1947 to 1957, then 1957 to 1968, then 2007 to current. Logs starting in 2007 indicate same time as 1968

Location of Salvage: Pearland, TX

Storage fee \$550.00 Per Month Storage Agreement Completed and Up To Date: N/A

Location of Avionics In Aircraft

Title Search Complete? Yes Date 3/18/2025

Location of Logbooks, Aircraft Records, Manuals, Keys, Bill of Sale: With Adjuster

Data plate removed? No

Adjuster/Contact Person: Jim Yearsich, 331.899.1162, jim.yearsich@mclarens.com

1947 Cessna 140 Reg: N12753

DOL: November 30, 2024
























YEAR 7-29-07 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR
	662.		0/5/11/0/4		
			////	Engine major of 4 this date- Crankease overhauled by CCrankoase	
				Crankease overhauled by CCrankosse	
				Services - Craukshaft, rods, camshaft	
				corred Hid whits lifters all certify	
				hi discrette Spocialties see vellow	Test
				tags for introj. Engine back togother	
				with all New MAIN + rods bearings,	1
				WITH GIT NEW MAIN TOUS VENTINGS	
				rod bolts, Nuts & Cotter Keys, 4 EA.	
	4			New Cyl Kits From Gibson Aviation	
				CHANNE ChromE cyls. with all New	
				parts (see yellow tags.) Mags harves	
				+ plugs- Kit From Stick, Carb repair	
104-				by Aircraft Access. Engine installed	
				on N2933N with all New MANDWAIE	
				Exhaust by STC 768/ SA2/SA648NE	
				Aerospace Welding Men Neapolis Next 1956 ?	

YEAR	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of
DATE	TIME		SERVICE	Technician or Repair Facility. (See back pages for other specific entries.)
		1500		INC. (see 337's FOR iNTO), added
				49ts Aeroshell Mineral oil Sout.
				TNC. (see 337's FOR INFO), added 49ts Aeroshell Mineral oil 50wt. installed overhauled McCauley
				Propeller / 1Ago/CF7/48 Starter 4
				Propeller (1A90/CF7148) STARTER & De 100 generator of H by Arkansas Aeronautics Accessories, (see yello tags.) Engine test run a made adjustin
				Active Accessories (can valle
				HEIONAUTICS ACCESSIVES, (SEE VENU
				TAGS, Engine TEST TUNG MHOE HOJWIN
				as heeded.
				William M. Stains
				A+P 413-96-3051
		10 11	4	See all tags. For S/B/S/L + A. P.s. comply with, in A/C record Marked Eng O/H.
				A D= comply with in Alc record
				made a della
				MITTIEC ENG UP.



	Continental		SERVICE	Technician or Repair Fa	ed with Name, Rating and Certificate Number of acility. (See back pages for other specific entries.)
]	~ ~ ~ ~ ~ ~ ~ ~ ~		C-	85-12F	26789-6-12
	July 22, 2008		Ta	ch Time 776.12	SMOH: 00.0
	approved revisi Rod and Main Crankshaft Sea serviceable asso and exhaust gui	ons, see Bearin I, Hoses embly. (ides, inta	form 337 gs, Rod B g, Gaskets, Cleaned and tke and exhibits. Pistons i	this date. Assembled olts and Nuts, Oil Po Seals, Hardware and O I inspected cylinders are aust valves, rocker shall	g 96-003 dated 3/8/1996 or later FAA Engine with the following new parts: cump Gears, Lifter Bodies, Camshaft, Clamps. Oil sump was replaced with and repaired as needed. Replaced intake fts, piston pins, rings, valve springs and conform to STC SE00979AT.
			Thomas	The Article Land	make so only
		- 3-			

YEAR	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries
DATE				to the specific entries
This day	te modified	engine	per STC	SE10076SC by installation of Glasses
accordan	ice with Sky	-Tec D	rawing No.	SE10076SC by installation of C12ST2/S starter in 71200 Revision I.R., dated 7-2-2002, or later FAA
approved	revision se	e form	337 this dat	te. STCSA00079NY incorporating AirWolf Remote Oil
Filter ad	anter installe	d this d	ate see air	frame log and form 337 this date. No other accessories
overhaul	ed or replace	ed at ow	ners reques	st and times on accessories. Reinstalled engine and test
ran in ac	cordance wi	th Conti	nental Serv	vice Bulletin: M89-7R1 and Overhaul Manual X30010.
all system	ns checked r	ormal.	Test flew f	or 2 hours, all systems checked normal. For information
on AD C	ompliance, s	ee AD (Compliance	Record. Use non detergent Aeroshell oil during break-
in period				
				Ad8 2013489
				- Dan July
9-13-0	9 1	soh	-fou i	Annual lusp Complete This
	_	- t-	Ene	in an as new EAR + Cont
	4	210	- 7	annual in sp Complete This in sp as pen FAR. + Cont ag Note SEBO8-4 C/wby Total and To be Airworthy
	6	ard	e - 1910	ig Note DE BOB- + 7WBY
	7	in e	. I fa	and To be Ainworthy
				Jack C. Kalanta
				Jane Contents
				/ Q & P 1128753



	TT. 2387.3
	Hobbs. 210.8
2933N	
essna 140 S/N 12753	
pate 10/2/2024	Engine TSO: 466.7
Engine C-85-12	S/N 26789-6-12
Maintenance Performe	
1 th Anni	hal/100 Hour Inspection.
Replaced Engine Inc. Replaced Spark Plug	S. P/N REM-40E
	and an Annual Hispection
I certify this	S Engine was Inspected in Accordance with an Annual Inspection and was a service and is approved for Return to Service.
	s Engine was Inspected in Accordance with the service. irworthy condition and is approved for Return to Service.
found to be in an Ai	
found to be in an A	
found to be in an A	John Welch 3654332 IA
found to be in an Ai	
found to be in an Ai	


	TACH	FLIGHT	TIME IN SERVICE	Technician or Re	endorsed with Name, Rating and Certificate Number pair Facility. (See back pages for other specific e
DATE					passes as a sure of the second
1			Any and who and the same and th		
_ Ces	sna		140		SER# 12753
7/22	2/2008		TAC	H 776.12	SER# 12753 TOTAL TIME 1618.72
per S Revis 3. T K008	SKY-TEC Drav STC SE10076 Sion I.R., date This date mod on single and the of 450 hor minimum thic	wing No. 7 SSC by ins d 7-2-200: dified airfra nd multi-er sepower (ckness AS	stallation of the stallation o	June 26, 2002, or land the control of the control o	77SC push-button starter system in accordance ater FAA approved revision and engine modified accordance with Sky-Tec Drawing No. 71200 n. 079NY Airwolf remote mounted oil filter kit AFC accorporating Teledyne Continental reciprocating C engine compartment firewall measured .021 equivalent (ref. CAR 3.624(b), FAR 23.119(h), ary 8, 1994 are required with installation.
Airwo	Revised equip	ment list a	and weight a	nd balance this date	any 8, 1994 are required with installation.
Airwo	Revised equip	ment list a	and weight a	nd balance this date	9



YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (<i>See</i> back pages for other specific entries.)
DATE		1		6.1.050
12/18/19	linstalle	d UA	2 Kinoiv	kybeacon using FAA STC SAO4362CH for installate
	permissi	or le	Her dat.	ed 2/18/2019 No Aictione Alteration regula
	No 519	mi-Sam	+ weigh	
1/19/20	110		,	c/w AD 61-25-01 torqueck man gear nots 100FH
1111/10	-1011			C/W AD 2017-16-01 ACK ELT 12MO INSPECTION ELT
-	TACH		1928.3	
	123.6	TT	1120,5	batteries are replaced with new clu AD 48
1				07 or stab attach bolt insprioofit
				C/W AD 48 25-03 100 FH wing insp
				dw AD 4750 02 100 FH faselage insp
				chu AD 4743 06 100FH Ailean Rib bilge locations
				DW AD 47 43 OB 100 FH Elevator spar hinge insp
-				
-				C/W AD 46 06 11 100 FH door post cracks SAIMIS
				Add sholder harness Aero Fabricators STC SA1412
				1.75 lbs x 2 at seat datum torm 351 this gat
				Sholder harness 3-Bar slide ret Aerotabricators AFG
	Thave in	P. The	AC IAW	for thustration of this determined groundthy and the

23	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number Technician or Repair Facility. (See back pages for other Specific.
DATE				Technician or Repair Facility. (See back pages for other specific entries
,-3	154.4			Poolitic entrie
				Removed and replaced + 1
				main spring using Univair P/A)
				mard ware ron
				Warren mosile floor Monds
24.0-	1			ARP 265108 TA
inspecti	cmber 2024,	Total Tim	e Airframe	7 222 1 (
mspecti	on Control			
	on. Control s	system co	mponents c	2,333.1 (owner corrected from previous entry). Owner opened aircraft hecked for freedom of movement and continuity. Description
inlet filt	er frame P/N	BA-4106	and BA-41	108 filter element with an Paris and continuity. Replaced engine air
inlet filt new. R	er frame P/N emoved fuel:	BA-4106 strainer bo	and BA-41	108 filter element with new. Replaced carburetor airbox P/N 641534 w
inlet filt new. Re inspecte	er frame P/N emoved fuel : d and repack	BA-4106 strainer be	and BA-41 owl for insparings. Ren	108 filter element with new. Replaced carburetor airbox P/N 641534 w section and replaced bowl gasket upon installation. Removed wheels to placed ELT Batteries and operationally checked in
inlet filt new. Re inspecte	er frame P/N emoved fuel : d and repack	BA-4106 strainer be	and BA-41 owl for insparings. Ren	108 filter element with new. Replaced carburetor airbox P/N 641534 w section and replaced bowl gasket upon installation. Removed wheels to placed ELT Batteries and operationally checked in
inlet filt new. Re inspecte 91.207 (er frame P/N emoved fuel d and repack d). Complied	BA-4106 strainer be wheel be d with Ce	and BA-41 owl for insparings. Repassna SL-79-	108 filter element with new. Replaced carburetor airbox P/N 641534 w spection and replaced bowl gasket upon installation. Removed wheels to blaced ELT Batteries and operationally checked in accordance with Fal-6 by removing throttle push pull ball joint P/N 0550158 and installation.
inlet filt new. Re inspecte 91.207 (Heim Re	er frame P/N emoved fuel : d and repack	BA-4106 strainer be wheel be d with Ce	and BA-41 owl for insparings. Repassna SL-79-	108 filter element with new. Replaced carburetor airbox P/N 641534 wheetion and replaced bowl gasket upon installation. Removed wheels to blaced ELT Batteries and operationally checked in accordance with 164 by removing throttle push pull ball joint P/N 0550158 and installation.
inlet filt new. Re inspecte 91.207 (Heim Re	er frame P/N emoved fuel and repack (d). Complied and End and h	BA-4106 strainer be wheel be d with Ce ardware s	and BA-41 owl for insp arings. Rep ssna SL-79- tack-up acc	108 filter element with new. Replaced carburetor airbox P/N 641534 who bection and replaced bowl gasket upon installation. Removed wheels to blaced ELT Batteries and operationally checked in accordance with FAI 6 by removing throttle push pull ball joint P/N 0550158 and installing ording to SL.
inlet filt new. Re inspecte 91.207 (Heim Re	er frame P/N emoved fuel d and repack (d). Complied od End and hamplied with:	BA-4106 strainer be wheel be d with Ce ardware s	and BA-41 owl for insp arings. Rep ssna SL-79- tack-up acc Exhaust M	108 filter element with new. Replaced carburetor airbox P/N 641534 who bection and replaced bowl gasket upon installation. Removed wheels to blaced ELT Batteries and operationally checked in accordance with FAI 6 by removing throttle push pull ball joint P/N 0550158 and installing ording to SL.
inlet filt new. Re inspecte 91.207 (Heim Re	er frame P/N emoved fuel and repack d). Complied od End and himplied with: AD 48-25-02 AD 48-25-02	BA-4106 strainer be wheel be d with Ceardware s 2 Welded 3 Drag W	and BA-41 bwl for insp arings. Rep ssna SL-79- tack-up acc Exhaust M ire Inspect	108 filter element with new. Replaced carburetor airbox P/N 641534 with new and replaced bowl gasket upon installation. Removed wheels to placed ELT Batteries and operationally checked in accordance with FAI 6 by removing throttle push pull ball joint P/N 0550158 and installing ording to SL.
inlet filt new. Re inspecte 91.207 (Heim Re ADs Con	er frame P/N emoved fuel and repack (d). Complied od End and himplied with: AD 48-25-03 AD 48-07-0	BA-4106 strainer be wheel be d with Ce ardware s 2 Welded 3 Drag W 1 Horizon	and BA-41 bwl for insparings. Reparings. Reparents SL-79- tack-up acc Exhaust Mire Inspect tal Stabilize	108 filter element with new. Replaced carburetor airbox P/N 641534 we section and replaced bowl gasket upon installation. Removed wheels to blaced ELT Batteries and operationally checked in accordance with FAI-6 by removing throttle push pull ball joint P/N 0550158 and installing ording to SL. uffler Inspect
inlet filt new. R inspecte 91.207 (Heim Rd ADs Con	er frame P/N emoved fuel and repack (d). Complied od End and h mplied with: AD 48-25-03 AD 48-07-0 AD 76-07-12	BA-4106 strainer be wheel be d with Ce ardware s 2 Welded 3 Drag W 1 Horizon 2R1 Igniti	and BA-41 owl for insparings. Reparings. Reparents ssna SL-79- tack-up acc Exhaust M ire Inspect tal Stabilize on Switch b	108 filter element with new. Replaced carburetor airbox P/N 641534 wheetion and replaced bowl gasket upon installation. Removed wheels to blaced ELT Batteries and operationally checked in accordance with FAI-6 by removing throttle push pull ball joint P/N 0550158 and installing ording to SL. uffler Inspect er Attaching Bolts inspect by operational check.
inlet filt new. R inspecte 91.207 (Heim Ro ADs Co	er frame P/N emoved fuel and repack (d). Complied od End and homplied with: AD 48-25-00 AD 48-07-00 AD 76-07-12 functionally of	BA-4106 strainer be wheel be d with Ce ardware s 2 Welded 3 Drag W 1 Horizon 2R1 Igniti	and BA-4) owl for insparings. Repsens SL-79 tack-up acc Exhaust M ire Inspect tal Stabilize on Switch b	108 filter element with new. Replaced carburetor airbox P/N 641534 we section and replaced bowl gasket upon installation. Removed wheels to blaced ELT Batteries and operationally checked in accordance with FAI-6 by removing throttle push pull ball joint P/N 0550158 and installing ording to SL. uffler Inspect er Attaching Bolts inspect by operational check.
inlet filt new. R inspecte 91.207 (Heim Ro ADs Co	er frame P/N emoved fuel and repack (d). Complied od End and homplied with: AD 48-25-00 AD 48-07-00 AD 76-07-12 functionally of	BA-4106 strainer be wheel be d with Ce ardware s 2 Welded 3 Drag W 1 Horizon 2R1 Igniti	and BA-4) owl for insparings. Repsens SL-79 tack-up acc Exhaust M ire Inspect tal Stabilize on Switch b	108 filter element with new. Replaced carburetor airbox P/N 641534 wheelection and replaced bowl gasket upon installation. Removed wheels to blaced ELT Batteries and operationally checked in accordance with FAI ording throttle push pull ball joint P/N 0550158 and installing ording to SL. uffler Inspect er Attaching Bolts inspect by operational check.
inlet filt new. R inspecte 91.207 (Heim Ro ADs Co	er frame P/N emoved fuel and repack (d). Complied od End and homplied with: AD 48-25-00 AD 48-07-00 AD 76-07-12 functionally of	BA-4106 strainer be wheel be d with Ce ardware s 2 Welded 3 Drag W 1 Horizon 2R1 Igniti	and BA-4) owl for insparings. Repsens SL-79 tack-up acc Exhaust M ire Inspect tal Stabilize on Switch b	108 filter element with new. Replaced carburetor airbox P/N 641534 wheelection and replaced bowl gasket upon installation. Removed wheels to blaced ELT Batteries and operationally checked in accordance with FAI ording throttle push pull ball joint P/N 0550158 and installing ording to SL. uffler Inspect er Attaching Bolts inspect by operational check. ects noted. This aircraft has been inspected in accordance with an Analysis worthy condition.
inlet filt new. R inspecte 91.207 (Heim Ro ADs Co	er frame P/N emoved fuel and repack (d). Complied od End and homplied with: AD 48-25-00 AD 48-07-00 AD 76-07-12 functionally of	BA-4106 strainer be wheel be d with Ce ardware s 2 Welded 3 Drag W 1 Horizon 2R1 Igniti	and BA-4) owl for insparings. Repsens SL-79 tack-up acc Exhaust M ire Inspect tal Stabilize on Switch b	108 filter element with new. Replaced carburetor airbox P/N 641534 wheelection and replaced bowl gasket upon installation. Removed wheels to blaced ELT Batteries and operationally checked in accordance with FAI ording throttle push pull ball joint P/N 0550158 and installing ording to SL. uffler Inspect er Attaching Bolts inspect by operational check.







IMPORTANT TERMS AND CONDITIONS

EXCLUSIONS

- 1. By placing a bid you accept and understand the following: that the salvage including wreckage and/or parts and/or documents and/or any other item sold pursuant to this Agreement are sold on an "as is, where is" with all faults basis and neither MYI Limited, trading as McLarens Aviation, nor the owner nor Insurers give any warranty, including any statutory warranties, or makes any express or implied or statutory representation as to the status or condition of the salvage or its suitability or fitness for any purpose or use whatsoever. For the avoidance of doubt, all terms implied under the Sale of Goods Act are excluded from this Agreement.
- 2. Neither MYI Limited, trading as McLarens Aviation, nor the owner nor Insurers shall have any liability or obligation whatsoever in respect of the salvage sold. In particular, any liability or obligation in tort, whether arising from negligence or otherwise, or in contract, express or implied pursuant to any statute or regulation for any losses whatsoever including but not limited to any direct or indirect or consequential losses, expressly arising from the purchase or subsequent use of the salvage.
- 3. The salvage is incident related and therefore MYI Limited, trading as McLarens Aviation, the owner and Insurers DO NOT warrant that the salvage is airworthy or serviceable.
- 4. In the event that your bid is accepted you warrant and undertake that the salvage shall be overhauled and recertified before it enters service (revenue or otherwise) in accordance with good aviation practice and any party undertaking such overhaul and recertification shall be made fully aware of the incident.
- 5. These exclusion provisions apply equally to purchases or users within the USA or outside of the USA.

INDEMNITY / HOLD HARMLESS

In the event you are the successful bidder, you undertake on behalf of yourself and any other party you are bidding on their behalf to indemnify and hold harmless MYI Limited, trading as McLarens Aviation, the Owner, Insurers and their employees, agents, assignees and shareholders, directors, officers and subsidiaries from and against any and all future claims arising out of the use of or existence of the salvage for any purpose in any jurisdiction whatsoever.

SEVERABILITY

Any clause of this Agreement which is declared unlawful, void or unenforceable by any competent authority or court with jurisdiction over this Agreement shall, to that extent, be deemed severed. All other provisions of this Agreement shall continue unaffected and remain in full force and effect.

Further I/we agree that we will make the necessary arrangements to have the Salvage storage and /or removal complete within thirty (30) days after the salvage award date.

GOVERNING LAW AND JURISDICTION

This Agreement and its interpretation shall be subject to the law of the State of Texas, U.S.A.