YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				Bearhawk S/N: 030-53/54-704 N1685 08/16/23 HOBBS: 517.7 TTIS: 517.7 Performed condition inspection on engine IAW FAR 43 appendix D. Changed oil and filter; inspected filter. Filled engine with Shell 15w50 oil and installed new filter. Checked mag timing. Tested ignition harness. Compression check: #1 - 79/80, #2 - 77/80, #3 - 78/80 #4 - 78/80. I certify this engine has been inspected IAW a conditional inspection and was found to be in a condition for safe operation at this time. Fah Copage 3 > 2 A A A G A+P
7				