DEPARTMENT OF TRANSPORTATION-FEDERAL AVIATION ADMINISTRATION STANDARD AIRWORTHINESS CERTIFICATE

UNITED STATES OF AMERICA

2 MANUFACTURER AND MODEL NATIONALITY AND 3 AIRGRAFT SERIAL NUMBER REGISTRATION MARKS CESSNA AIRCRAET

N190CG 190 7634

UTILITY

4 CATEGORY

NORMAL

5 AUTHORITY AND BASIS FOR ISSUANCE

This airworthiness certificate is issued pursuant to 49 U.S.C. § 44704 and certifies that, as of the date of issuance, this aircraft has been inspected and found to

conform to its type certificate and be in a condition for safe operation. This aircraft meets the requirements of the applicable airworthiness standards in Annex 8

None.

to the Convention on International Civil Aviation, except as follows:

6 TERMS AND CONDITIONS

Unless sooner surrendered, suspended, revoked, or a termination date is otherwise established by the FAA, this airworthiness certificate is effective as long as maintenance, preventative maintenance, and alterations are performed per the applicable Federal Aviation Regulations and the aircraft is registered in the United States.

DATE OF ISSUANCE FAA REPRESENTATIVE (R)04-11-69 KEITH R SERKES


DESIGNATION NUMBER 707546742

Any alteration, misuse, or reproduction of this certificate for a fraudulent purpose may be punishable by certificate revocation, fine, and / or imprisonment.

THIS CERTIFICATE MUST BE DISPLAYED IN THE AIRCRAFT PER THE APPLICABLE FEDERAL AVIATION REGULATIONS. FAA Form 8100-2 (11-2016) Previous Edition Dated 04-11 May be Used Until Depleted

_	N190CG DATE: 04/19/2023 TACH: 7.0. INSTALL NEW CONCORDE RG35AXC BATTERY. ROBERT D. FENNER A&P3282552	t eratio umber of c entries
	Butterfly Aviation, Inc. Goodland, KS. DATE: 08/01/2023 TACH: 28.6. TROUBLE SHOOT RIGHT HAND BRAKE GRABBING WHEN APPLYING RUDDER. FOUND PARK BRAKE CABLE ADJUSTED TO TIGHT. ADJUST RIGHT HAND CABLE TO MATCH LEFT HAND CABLE WHEN APPLYING PARK BRAKE. CHECK AND SET MAIN LANDING GEAR ALIGNMENT I/A/W CESSNA 195 MAINTENANCE MANUAL. TAXI TEST – PERFORMS SATISFACTORY. SERVICE TAIL STRUT W/NITROGEN. SERVICE TAIL WHEEL TIRE W/AIR. ROBERT D. FENNER A&P3282552 N190CG Butterfly Aviation, Inc. Goodland, KS. INSPECT CABLES, PULLEYS, BELLCRANKS, LIGHTS, PITOT HEAT, STALL HORN, CHARGE BATTERY, INSPECT BRAKE PADS, DISCS, SERVICE BRAKES. CHECK DO POSTS, INSP SPAR PER AD, OPERATE HEATER. CHECK ELT PER FAR91 207(d), REPLACE BATTERY, EXP JULY 2026. REPAIR ENGINE BAFFLES, REROUTE ENGING C/W AD63-20-02 WING SPAR PARA C, AD84-10-01R1 FUEL BLADDERS-NO LEAKS, AD11-10-09 SEAT TRACKS, PINS, ROLLERS, OK, AD17-06-03 HEATER-DUE 03/2025 I CERTIFY THAT THIS AC/ENGINE HAS BEEN INSECTED IN ACCORCDANCE WITH ANNUAL /100HR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. JOHN COLLETT AI 1530026	NE 9°S
	STATION. JOHN COLLETT AI 1530026	

ENGINE LOG



ENTER HERE GENERAL DATA WITH REFERENCE TO "LINE" AND "PERIODIC" INSPECTIONS—ACCIDENT A CERTIFICATED MECHANIC AND WERHAULS. ALL DATA MUST BEAR THE ENDORSEMENT	5-
03/01/2023 T 7.0 TT 3435.9 TSOH UNK, TIME SINCE REPAIR 230.4 LUBE PROP/KIDNEYS SHELL #5 GREASE, INSP PROP & SPINNER	OF
John Collett HY 153 coll	
06/04/2024 T 29.5 TSREPAIR 252.9, TT UNK INSPE PROP AND SPINNER, LUBE, SHELL #5	5